

**UNITED KINGDOM**  
**SIDEWAY-FORCE SKID RESISTANCE SURVEY DEVICES**  
**ACCREDITATION TRIAL SUMMARY TEST CERTIFICATE**

Report No: 0122SKID/KX07 YXH Issue 4

**REGISTRATION NUMBER: KX07 YXH**  
**TRIAL Reference No: 21**

Operated by **Surrey County Council**  
Of Merrow Laboratory, Merrow Lane, Guilford


has participated in a United Kingdom Sideway-Force Coefficient Routine Investigation Machine Accreditation trial on **10 April 2018** at MIRA Proving Ground, Watling Street, Nuneaton, Warwickshire, CV10 0TU under the supervision of TRL.

The above machine has been tested against the criteria specified in Accreditation and Quality Assurance of Sideways Force Skid Resistance Survey Devices document<sup>1</sup> dated July 2016.

This machine has successfully met the mandatory criteria. Some Network Authorities may also require specific level of performance in some or all of the additional tests. The performance of this machine in each test is summarised in the Annex to this test certificate.

This certificate supersedes any previous certificates issued by TRL.

Signed on 25 April 2018 for and on behalf of TRL Limited



Patrick Werro

Valid From: 13 April 2018  
Date of expiry: 13 May 2019

<sup>1</sup> This document is available from TRL or from the following website  
[http://www.ukroadsliasongroup.org/en/asset-condition/road-condition-information/data-collection/skid-resistance/Sideway\\_force\\_skid\\_resistance\\_survey\\_devices/index.cfm](http://www.ukroadsliasongroup.org/en/asset-condition/road-condition-information/data-collection/skid-resistance/Sideway_force_skid_resistance_survey_devices/index.cfm)  
please contact [accreditation&qa@trl.co.uk](mailto:accreditation&qa@trl.co.uk) for further details



## Test Certificate Annex

The following parameters must be passed to successfully meet the requirements of the accreditation trial.

Tested Parameter	Left wheel	Right wheel
<b>Skid Resistance</b>		
Between run standard deviation	Pass	Not Assessed
Between equipment standard deviation	Pass	Not Assessed
<b>Distance measurement and Vehicle Speed</b>		
Distance measured	Pass	
Vehicle Speed	Pass	
<b>Test wheel weight and water flow</b>		
Test wheel weight	199.7	Not Assessed
Water flow rate	Pass	Not Assessed
Water flow direction	Pass	Not Assessed
<b>* Comments:</b>		
Distance assessed against push button criteria.		

The following parameters were also tested/reviewed. They are not currently mandatory requirements, however some Network Authorities may also require specific level of performance in some or all of these additional tests.

Tested Parameter	Performance
OSGR coordinate measurement	Not Assessed
Altitude measurement	Not Assessed
Data alignment performance	Satisfactory
.S10 file format	Satisfactory
.LOC file format	Satisfactory
.RCD file format	Not Assessed
.BCD file format	Not Assessed
<b>Comments:</b>	